



- Provides optimum moisture output, performance, and durability
- Replaces Aprilaire, Honeywell, Carrier, Bryant, Lennox, ICP, and others
- Made from quality materials in the USA

Description

ClenAir Universal Humidifier Panels provide optimum moisture output, performance, and durability. They replace Aprilaire, Honeywell, Carrier, Bryant, Lennox, ICP, and others. Made from quality materials in the USA.

Directions

1. Turn off and disconnect electric and water supply.
2. Remove and discard old humidifier panel and clean any lime deposits left in humidifier
3. Replace with your new humidifier panel.
IMPORTANT: If marking is on panel, it must be up!
4. Reassemble unit and reconnect water and electric.

For best performance, change at least twice per season, maybe more depending on water conditions and frequency of use.

Humidifier Panels

Universal Humidifier Panel Replacements



Packaging	Nu-Calgon #	ClenAir #
#10 Size	61250	CA10
#35 Size	61252	CA35

The **CA10** can be used to upgrade the following humidifier models:

Aprilaire®:

110, 220, 500, 500A, 500M, 550, 550A, 558

Bryant®:

HUMBBSBP2212, HUMBBSBP2312, HUMBASBP2312, HUMBBSBP2412, HUMBASBP2412

Carrier®:

HUMCCSBP2212, HUMCCSBP2312, HUMCASBP2312, HUMCCSBP2412, HUMCASBP2412

Lennox®:

WB2-12, WB2-12A

Totaline®:

P110-SBP2212, P110-SBP2312, P110-SBP2412

Honeywell®:

HE220A/B, HE225A/B

Hamilton®: 12HF

ICP®:

HMICSB12A

The **CA35** can be used to upgrade the following humidifier models:

Aprilaire®:

350, 360, 560, 560A, 568, 600, 700, 760, 760A, 768

Bryant®:

HUMBBLBP2217, HUMBBLBP2317, HUMBALBP2317, HUMBBLBP2417, HUMBALBP2417, HUMBBLFP1218, HUMBBLFP1318, HUMBALFP1318

Carrier®:

HUMCCLBP2217, HUMCCLBP2317, HUMCALBP2317, HUMCCLBP2417, HUMCALBP2417, HUMCCLFP1218, HUMCCLFP1318, HUMCALFP1318

Lennox®:

WB217, WP218

Totaline®:

P110-LBP2217, P110-LBP2317, P110-LBP2417, P110-LFP1218, P110-LFP1318

Honeywell®:

HE260A/B, HE265A/B, HE360A/B, ME360, HE365A/B

ICP®:

HMICLF18A, HMICLB17A

